TECHNICAL INFORMATION

Date: 1/9/89
Issue: T-31

TO: Dealer Technical Department

FROM: RISO, Inc. Technical Department

SUBJECT: Modification Kit: (New style upper discharge roller/sticker sheet)

MODIFICATION SCHEDULE: As Necessary

SYMPTOM: 1) Master jams entering disposal box or has a tendency to stick or wrap around upper discharge rollers.

2) Master is not removed from the drum causing double master on drum surface.

MODIFICATION: Replace "upper discharge roller" part #002-14111-101 and replace "sticker sheet" part #002-12134-104 as needed.

* New style upper discharge roller can be easily identified as being blue in color and teflon coated.

Additional supplies to modify all the machines in the field will be sent to dealers free of charge, according to serial number population at the end of January.

Any questions should be referred to RISO Technical Department at 1-800-777-9877.

RISO

300 Rosewood Drive, Suite 210, Danvers, MA 01923 Telephone (508) 777-7377 Fax (508) 777-2517